



CSV-3104D

USB 3.2 GEN 1 4K MINI DOCKING STATION
Quick Installation Guide



www.club-3d.com



Installing the Drivers/Software

Windows™ OS

NOTE: DO NOT connect the adapter to the computer before completing the driver installation.

1. Download the latest driver from our website: www.club-3d.com
Or from www.displaylink.com
 2. How to install driver (DisplayLink) software:
You will find an extensive installation manual on the Displaylink website.
Go to www.support.displaylink.com and select the request operating system.
-

Mac® OS X™

NOTE: DO NOT connect the adapter to the computer before completing the software installation.

1. Download the latest software from our website: www.club-3d.com
Or from www.displaylink.com
 2. How to install driver (DisplayLink) software:
You will find an extensive installation manual on the Displaylink website.
Go to www.support.displaylink.com and select the request operating system.
-

Making the Connection

1. Connect the Docking Station to a HDMI* or/and DVI monitor and a computer.
The screen may temporarily go black or flash during this process.
2. Connect the USB peripherals, Ethernet, speaker and microphone to the corresponding connectors.

NOTE: When using the HDMI and the DVI connector simultaneously, the HDMI connector will not be able to reach 4K resolutions.

