


CSV-1564/CSV-1564W65/CSV-1564W100 QUICK INSTALLATION GUIDE



Thank you for purchasing our CSV-1564 / CSV-1564W65 / CSV-1564W100 Product.


After unpacking the product, please make sure you have all the items provided and checked for any damages. In case of any missing/damaged parts please inform your supplier immediately.

You should have:

- A CSV-1564 or a CSV-1564W65 or the CSV-1564W100 Docking Station
- PowerSupply (PD 3.0 supported power charger is variable from 3A to 5A according to your purchased option)
- 2x USB Type C cable: 1x connection to Host 27cm / 0.886ft, 1x RED cable USB type C for charging to PowerSupply 1 m / 3.28 ft
- Quick Install Guide

Please make sure that:

- Your Host System has the latest drivers updates installed
- Your Host System supports DisplayPort Alt Mode
- Follow the QIG installation step



- **1.** Please connect the black USB type C cable clicked onto the Dock and connect, the angled connector, to the Dock at that side of the Dock, connect the other side of that cable to the USB Type C port of your NoteBook/Host system.
- 2. Connect your preferred Display(s) to the designated connector(s) and power on your Display unit(s), peripherals, ethernet and/or sound devices
- **3.** Connect the RED USB Type C cable in the Power Charger into the USB Type C connector and the other side to the Marked" RED" USB Type Connector on the Dock.
- 4. Now Plug the Power Charger in a wall socket and switch the Dock ON, the BLUE indicator should be lit!

No need to connect your Host system to the Power Charger, our Dock will Dynamically Charge your Host system. You're ready to start working and enjoy the full benefits of our Dock.

Warning Safe Usage: Only to be used at altitude 2000 meters/6562 feet and below.

For any Questions please check our forum section on our website www.club-3d.com